

## Product Technical Bulletin: 19T003R0

(YY=year, T=SBU, 001=Count, R1=Revision Level)

**SUBJECT:** ESP-Me Indoor Transformer Change

## **MODELS AFFECTED:**

| Model      | Product ID | Change Description |
|------------|------------|--------------------|
| ESP4MEI    | F55100     | Transformer Change |
| ESP4MIXFMR | 635640     | Discontinued       |

**IMPLEMENTATION DATE CODE:** Beginning of June 2019

## **Introduction:**

The ESP-Me Indoor controller F55100 is changing from a plug-in transformer to a transformer built into the controller with an attached power plug. This is similar to other Rain Bird controller models that include the ESP-TM2 and the ESP-ME3.

The ESP-Me Indoor controller will continue to be rated for indoor use only, without a locking door or the weather resistant exterior found in other outdoor controllers.



## **Service Part Information:**

The transformer plug-in service part for the ESP-Me Indoor controller has been discontinued.

19T003(R0) Page 1 of 1