



Product Technical Bulletin

DVF Valves Bonnet Change

January 26, 2024

SUBJECT: DVF Valves Bonnet Change

MODELS AFFECTED:

Product ID	Model	Description
B72421	100DVF	100DVF NPT
B72611	100DVFSS	100DVFSS
B70311	I100DVF	100-DVF BSP

IMPLEMENTATION DATE CODE: January 22, 2024

Introduction:

Beginning January 22, 2024, the 100DVF, 100DVFSS, and I100DVF (BSP) will feature an enhanced bonnet with captive, multidrive screws. The new bonnet and screws will provide faster bonnet removal and enhanced ease of access to service the valve diaphragm. Phillips head screwdriver, slotted head screwdriver, or nut driver can all be used to open the valve and access the diaphragm.

Interchangeability:

The enhanced bonnet is backwards compatible with older model DVF bodies and can be used to service valves previously installed.

Service Part Information:

The part number for the 100DVF, 100DVFSS, and I100DVF are not changing.

Special Instructions:

This is a rolling change to the DVF bonnet. No model number, part number or pricing changes are expected.

Rain Bird Corporation

6991 E. Southpoint Rd., Tucson, AZ 85756

(800) 282-1933 Fax: (800) 843-4162

[Privacy Policy](#) | [Unsubscribe](#) | [View in Browser](#)