


APAS-075 / APAS-100

ECV-075 / ECV-100



Please note: Old solenoid B60592 shown and associated actuator are no longer available. To replace use B60587 (See figure B).

Ref.	Part Description	APAS-075 ECV-075	APAS-100 ECV-100
1	SOLENOID REPLACEMENT KIT	B60599	B60599
-	SOLENOID O-RING	235532	235532
-	SOLENOID FILTER	(170368)	(170368)
2	PISTON REPAIR KIT	B40685	B40685
3	Piston	(208997)	(208997)
4	Piston Spring	(205829)	(205829)
5	Filter	(206092-01)	(206092-01)
6	Upper Bonnet O-Ring	(202850-05)	(202850-05)
7	Lower Bonnet O-Ring	(205269)	(205269)
8	CAP, COVER & PISTON ASSEMBLY	210067	210067
9	Cap & Cover Assembly	(140134)	(140134)
10	Gasket	(235309)	(235309)
11	Piston Vacuum Breaker	(231917)	(231917)
12	Sealing Washer	(234932)	(234932)
13	Body	233192	233195
(A)	AVA-1 Actuator & Piston Assembly	145235	145235

Note: Part numbers enclosed in brackets ( ) are not available individually, but may be sold in assemblies or kits.